




10
60 min abkühlen lassen
allow to cool
laisser refroidir
dejar enfriar




11
Küvette um 180° drehen
Turn tube upside down
Retourner tube
Girar tubo



12
Säuber
Clean
Nettoyer
Limpiar



13
Null messen
Measure blank
Lecture blanc
Lectura blanco



14
Messung
Measurement
Mesure
Medición